

<b>Date</b>	09 Jan 2018	<b>Service Note #</b>	OPT-DISS-3042	<b>Updated</b>	NA
<b>Product</b>	Opt-Diss		<b>Created By</b>	J. Yangco	
<b>Description</b>	Software Rev. 3.0.1 Operation Manual not updated				

<b>Release</b>	<input checked="" type="checkbox"/>	<b>Internal</b>	<input checked="" type="checkbox"/>	<b>Distributors</b>	<input checked="" type="checkbox"/>	<b>Customers</b>
----------------	-------------------------------------	-----------------	-------------------------------------	---------------------	-------------------------------------	------------------

<b>Parts Required</b>	<b>Serial Numbers Affected</b>
None.	All

**Reason:** During the final software build, the older revision of the operation manual was used. The software operation manual needs to be updated from Rev. 3.0.0 to Rev. 3.0.1.

### Solution / Action

Visit Distek Member Center (<http://distekinc.com/>) to get a PDF copy of the Opt-Diss Software Operation Manual Rev. 3.0.1.



**Before proceeding, make sure to close the software application before updating the operation manual.**

Once a PDF copy is obtained, rename the file to “OPTDISS Manual” then copy the renamed file to the location where the “OPT-DISS” folder is located (default location: C:\Program Files (x86)\Distek\OPT-DISS).