

Date	19 Oct 2015	Service Note #	3200-2072	Updated	NA
Product	sensIR 3200		Created By	J. Yangco	
Description	Intermittently Prints Incorrect Number of Total Pages				

Release	<input checked="" type="checkbox"/>	Internal	<input checked="" type="checkbox"/>	Distributors	<input checked="" type="checkbox"/>	Customers
----------------	-------------------------------------	-----------------	-------------------------------------	---------------------	-------------------------------------	------------------

Parts Required	Serial Numbers Affected
None	All instruments with Firmware Rev. 1.04 and older

Intermittently Prints Incorrect Number of Total Pages

Reason: Occasionally some end-users report test reports being printed with the total number of pages printed incorrectly.

Solution / Action

Distek is looking into this intermittent issue and will provide a patch upgrade on the user interface application.



There are no additional data missing and the current report does print all the required information.