

<b>Date</b>	26 Jun 2015	<b>Service Note #</b>	OPT-DISS-2057	<b>Updated</b>	NA
<b>Product</b>	Opt-Diss 405		<b>Created By</b>	J. Yangco	
<b>Description</b>	3880-OPTDISS-IQ-H Software Hardware Installation Validation Document Rev. 1.13				

<b>Release</b>	<input checked="" type="checkbox"/>	<b>Internal</b>	<input checked="" type="checkbox"/>	<b>Distributors</b>	<input checked="" type="checkbox"/>	<b>Customers</b>
----------------	-------------------------------------	-----------------	-------------------------------------	---------------------	-------------------------------------	------------------

<b>Parts Required</b>	<b>Serial Numbers Affected</b>
None.	All instruments that use software Rev. 2.0.0 and later

## Typographical Error in Opt Diss Qualification Document

The hardware installation qualification document 3880-OPTDISS-IQ-H contains a typographical error. The section 8.7.4 on page IQP-19 references two temperatures that are missing their negative sign. The temperatures are 30 and 70 degrees respectively. The camera must operate at a negative temperature to function optimally. The typographical error will be corrected and this memo should be filed with each qualification document until that time. The person(s) completing the document should make reference to this memo as required by GLP guidelines.

Validation and Support Manager

